

FRAME RAILS

NOT TO SCALE

FORWARD

CENTERLINE OF LOWER
STEERING BOX BOLT

Hole for
Pinion shaft

6.81

4.4

POWER CAMARO

